#### KEEPING THINGS GOING

## PREVENTATIVE MAINTENANCE, INSTRUMENT REPAIR AND TROUBLESHOOTING

PQAO TRAINING 2019


MATT RAZAVI, CARB

INSTRUMENT TECHNICIAN

#### WHAT DO THESE HAVE IN COMMON?








#### SIP

is an acronym for

State Implementation Plan

(l)

by allacronyms.com





#### **OVERVIEW**

- Elements of an Effective Maintenance Program
- Preventative Maintenance
- Instrument Repair
- Equipment Replacement
- > Troubleshooting
- Instrument Repair (PROTIPS)
- Takeaways!
- **Exercises**

# ELEMENTS OF AN EFFECTIVE MAINTENANCE PROGRAM

Established Maintenance Schedules

Sources of Repair

Equipment Replacement Schedule

Legally Defensible

Maintenance Records Maintain
Spare
Equipment
and Parts

**Equipment Inventory** 

#### PREVENTATIVE MAINTENANCE

- ► What is PM?
- Ongoing Element of QC
- Scheduled Activities
- **Every Organization**
- Review and Update



#### INSTRUMENT REPAIR

- Repair/test facilities
- Equipped to test, repair and troubleshoot
- Dedicated area to repair/test
- No modification of equipment
- In-house repair vs service agreements



#### EQUIPMENT REPLACEMENT

- ► Life Span
- >Old/Outdated equipment
  - Performance quality
  - Too costly to maintain
  - Potential loss of DATA
  - No support
- New equipment features



#### TROUBLESHOOTING

- Instrument manuals
- Remote monitoring
- Vendor provided support
- Contact SME's

### INSTRUMENT REPAIR (PROTIPS)

- Power
- >EASY > HARD
- Other instruments
- **Configuration**
- Diagnostic values

- >Operating Principle
- Ferror and Warning
- > Power Outage
- Who to Contact
- Maintenance RECORDS

#### TAKEAWAYS!!

HOW IS OUR AGENCIES PM PROGRAM?

► IS IT ADEQUATE?

WHAT CHANGES DO WE NEED TO MAKE?

#### TROUBLESHOOTING EXERCISES

#### **EXAMPLES**

- Thermo Scientific 2025i
- > TAPI 400 Ozone
- Met-One BAM 1020



### **THERMO 2025I**

Shuttle Error

```
CTRST SSET
```

#### FIRST STEPS

- Do I have other issues or problems?
  - Failed Leak Check
- Are there error flags/codes?
  - Hall Sensor Error
- What does Instrument Manual state?

#### **CORRECTIVE ACTIONS**

- Technical Bulletins
  - Partisol iSeries Shuttle Errors initial conditions
  - TS0043 2025i Low Pump Pressure
    Sintered Filter Replacement
- Better Upkeep and Maintenance

```
PRESSURES

AMBIENT PRES 750 mmH9

AMB PR A 750 mmH9

FILTER PRES 750 mmH9

FLT PR A 750 mmH9

PUMP PRES 0.0 atm

AUDIT 16:37

AUDIT 16:37

AUDIT MODE

>ADVANCE FILTER OFF

AUDIT


VIEW AUDIT HISTORY

LEAK CHECKS

CTRST SSET FLTID STATE
```

#### TAPI 400 OZONE ANALYZER

►O3 Reading Drift



#### FIRST STEPS

- Do I have other problems?
- Are there error flags/codes?
  - LAMP STABILITY WARN.
  - SAMPLE FLOW WARN.
- What does Instrument Manual state?

#### **CORRECTIVE ACTIONS**

- Instrument Manual Trouble Shooting
  - ➤ Sec. 12. TROUBLESHOOTING & SERVICE
- Better Upkeep and Maintenance

#### BAM 1020 COMMON ISSUES

- Failed Leak/Flow Check
- Membrane Errors

#### FIRST STEPS

- What other problems do I have?
- Are there BAM error flags/codes?
  - N-Nozzle Error,
  - F-Flow Error
  - R-Reference Membrane Error
- Maintenance/Repair history?

### **CORRECTIVE ACTIONS**

- Instrument Manual
  Troubleshooting
  - Sec. 7. Maintenance, Troubleshooting
- Better Upkeep and Maintenance





#### **QUESTIONS?**

**MATT RAZAVI** 

MATT.RAZAVI@ARB.CA.GOV (916) 324 7332